

MACHINERY & BOOTS MUST BE CLEANED BEFORE ENTRY INTO EACH PERMIT
PERMITS 34,35,36 MUST HAVE EQUIPMENT INSPECTED BY R MUELLER AND BE POWERWASHED AND CLEANED WITH BLEACH SOLUTION

672000

RGE 3 W5M

674000

676000

678000

RGE 2 W5M

2D and 3D Seismic line

6003000

6001000

TWP 59


5999000

6003000

6001000

TWP 59

5999000



This culture of the map was derived from public domain sources. Under no circumstances shall the user be liable for conditions and/or damages that may be present on this map or any data thereon based upon the information displayed.
This map has been produced for the sole use of the intended recipient. It is not to be used for any other purpose without the consent of the data provider. © 2014, Schlumberger Technology Corporation.

672000

RGE 3 W5M

674000

676000

678000

RGE 2 W5M